



Visit us on the web at www.cardinalcircuit.com
 Phone: 614-327-2601 Email: brad@cardinalcircuit.com

Available from Cardinal Circuit...
Agilent SP50 AOI Spare Parts - Brand New

Parts are brand new and in original packaging.

PART NUMBER	DESCRIPTION	QUANTITY ON HAND
453030300170r	USB cables	2
4B578	PLC reset switch box	2
4B583	PLC reset switch	1
5186-0034	Motor	2
5186-0801	Board sensor cable	1
5186-1295	Board sensor/bracket	1
5186-2092	Relay	2
5186-2142	Flag sensor	1
5186-2143	Proximity sensor	2
5186-2238	Air line filter	3
5186-2964	Light tower bulb	1
5186-3732	Euresys Grablink PCI	1
5186-4621	X,Y,Z Servo AMP	1
5186-4628	Driver	1
5186-4699	PCA, MEI controller	1
5186-4928	Fuse 15A	3
5186-4929	Fuse 2A	3
5186-5280	Conveyor belt	5
5186-5281	Conveyor bearing	10
5186-5724	Laser Calibration Kit	1
5186-5730	Spare PC	1
5186-5740	Software	1
5188-6698	Software	1
6H206	PLC Reset Blue	0
	Conveyor spacer	1